

Inspection Photos  
Location Name: Nielson #3  
API: 05-007-06116



Stained soil beneath load out valve and below hammer union on flow line.



Oil stained AST.

**Inspection Photos**  
**Location Name: Nielson #3**  
**API: 05-007-06116**



**Oil staining on AST near thief hatch.**



**Leaking hammer union on flow line.**



**Inspection Photos**  
**Location Name: Nielson #3**  
**API: 05-007-06116**



**Stained soil beneath tank valve.**



**Nielson #3 well head and pump jack.**



**Inspection Photos**  
**Location Name: Nielson #3**  
**API: 05-007-06116**



**Nielson #3 well head with oil staining.**



**Oil stained well head and impacted soil.**



**Inspection Photos**  
**Location Name: Nielson #3**  
**API: 05-007-06116**



**Unused 55 gal. drum chemical injection system.**



**Proximity of tank battery to well head.**