

Inspection Photos
Location Name: Chavez #2
API: 05-007-06136



Chavez #2 well head and pump jack.



Chavez #2 pump jack and electric prime mover.

Inspection Photos
Location Name: Chavez #2
API: 05-007-06136



Well head and area below valve are stained.



Oil stained well head and soil.