

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2018

Submitted Date:

04/18/2018

Document Number:

688800073**FIELD INSPECTION FORM**Loc ID 320854 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 900Name of Operator: ALAMOSA DRILLING INCAddress: 8150 N. CENTRAL EXPY - STE 750City: DALLAS State: TX Zip: 75205-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Martinez, Albert	(970) 264-2575	we5tgang@yahoo.com	All Inspections
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205242	WELL	SI	05/01/2015	OW	007-06120	CHAVEZ 1	EI

General Comment:

On April 17, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Inc. Chavez #1. For the most recent field inspection report of this facility, please refer to document #685300988.

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	AST has NFPA placard and is labeled with contents and capacity.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Free standing sign near AST only lists Chavez #1 as contributing well.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐

Spills:				
Type	Area	Volume		
Crude Oil	Tank	<= 1 bbl		
Comment:	Stained soil below load out valve on AST.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 05/18/2018
Crude Oil	WELLHEAD	<= 1 bbl		
Comment:	Stained soil around well head.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 05/18/2018

In Containment: No

Comment: ☒ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog wire enclosure around pump jack and well head.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Supply shed.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:		Date:	

Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		37.018081,-106.875100
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	205242	Type:	WELL	API Number:	007-06120	Status:	SI	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On April 17, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Inc. Chavez #1. For the most recent field inspection report of this facility, please refer to document #685300988. During this field inspection it was noted: An area of approximately 4' by 7' around the well head is stained with oil. The area beneath the truck load out valve on the AST is stained with oil.	hughesj	04/18/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800074	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4438600