

Inspection Photos
Location Name: Albert Martinez #1
API: 05-007-06253



Albert Martinez #1 and Nielson #4 tank battery.



Stained soil beneath load out valve.

Inspection Photos
Location Name: Albert Martinez #1
API: 05-007-06253



Albert Martinez #1 pump jack and well head.



Well head and surrounding soil is stained with oil.