



**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road to Rothe 1-14 well (API#: 05-123-18429) is adequate.		
Corrective ActionL			Date:
Type	Access		
comment:	Access road to Rothe 1-15 well (API#: 05-123-23933) is adequate.		
Corrective ActionL			Date:
Type	Main		
comment:	Adequate		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Facility Battery sign shows 2 wells that have been P&A'd 1.) Rothe 1-11 (API# 05-123-18428) 2.) Hertzke 1-12 (API# 05-123-20036)		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		
			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_  
 Comment:   
 Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Has 6' chain link fence.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Rothe 1-15 (API# 05-123-23933) has iron panel fence. Rothe 1-14 (API# 05-123-18429) has iron panel fence.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Has 6' chain link fence.		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	East ECD has barbed wire fence. West ECD has 6' chain link fence.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	2 wells are commingled into this separator. 1.) Rothe 1-14 (API# 05-123-18429) 2.) Rothe 1-15 (API# 05-123-23933)		
Corrective Action:		Date:	
Type: Emission Control Device	#		
Comment:	West ECD: Separator VOCs East ECD: Tank VOCs		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	2 - Plunger lifts. Rothe 1-14 (API# 05-123-18429) Rothe 1-15 (API# 05-123-23933)		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	OTHER	OTHER		,
Comment:	Produced water vessel / vault has been removed. Site is currently under status of Form 27 Site Investigation & Remediation as of 02/05/2018.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	Unknown. Water vessel has been removed.
Other (Type)	Unknown. Water vessel has been removed.

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms are in a state of remediation with temporary safety fencing surrounding oil tank.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.430040,-104.834100
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Berms are in a state of remediation with temporary safety fencing surrounding oil tank.</a>				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 250626 Type: WELL API Number: 123-18429 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead appears plumbed to surface.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 285032 Type: WELL API Number: 123-23933 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead appears plumbed to surface.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
As this facility is currently undergoing Form 27 Site Investigation & Remediation, a follow-up inspection will be required. Please notify COGCC Area 121 Inspector Bret Evins at (970)420-6699 when work is completed.	evinsb	04/20/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200051	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4441197">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4441197</a>
691200052	Form 27 Site Investigation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4441198">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4441198</a>