

# Inspection Photos

API: 05-067-07789

Operator: XTO ENERGY INC.

Inspection Date: 3/21/2018



**Photo 1. View of the project area from the northeastern corner facing center.**



**Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is comprised of a grasses such as smooth brome (*Bromus inermis*) and western wheatgrass (*Pascopyrum smithii*).**



**Photo 3. View of the eastern portion of the interim reclamation area from the northeastern corner facing southward.**



**Photo 4. View of the southern portion of the project area from the southeastern corner facing westward. Erosion is occurring in the southern project area where concentrated stormwater flows off of the well pad.**



**Photo 5. View of another area in the southern project area where concentrated stormwater is eroding fill slopes.**