

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2018

Submitted Date:

04/17/2018

Document Number:

685304595**FIELD INSPECTION FORM**Loc ID 313628 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10434Name of Operator: ATOM PETROLEUM LLCAddress: 3323 N MIDLAND DR #113City: MIDLAND State: TX Zip: 79707**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Roy, Catherine		catherine.roy@state.co.us	
Hughes, Jim		jimo.hughes@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297954	WELL	SI	05/18/2016	OW	083-06653	DOERFER 1-5	SI

General Comment:[Inspection completed as part of well plugging operation.](#)[See link at end of report for path to downloadable inspection pictures.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment	# 0		
Comment:	Electrical equipment. Removed in perparation for plugging work.		
Corrective Action:		Date:	
Type: Pump Jack	# 0		
Comment:	Removed in perparation for plugging work.		
Corrective Action:		Date:	
Type: Flow Line	# 0		
Comment:	Flow line from Doerfer 1-5 to riser at Doerfer 2 plugged and abandoned in perparation for plugging work.		
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:	Removed in perparation for plugging work.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 297954 Type: WELL API Number: 083-06653 Status: SI Insp. Status: SI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685304616	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4442659