

# Final Reclamation and Stormwater Inspection

April 20, 2018

Operator: PETROSHARE CORPORATION- 10454

API: 05-039-06428

Inspection Document #: 682403498

Elbert County, CO

SESE Section 19 T6S R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: RMPCO-EVERETT-UPRR #1

API: 05-039-06428



Google Earth aerial imagery taken 9/29/1999 illustrating well and battery location during operations.

## Inspection Photos

Location Name: RMP CO-EVERETT-UPRR #1

API: 05-039-06428



Google Earth aerial imagery taken 6/15/2010 illustrating well and battery location after the location was plugged in 2003. Both the well and battery locations do not meet Rule 1004 standards.

## Inspection Photos

Location Name: RMP-ECO-VERETT-UPRR #1

API: 05-039-06428




Photo reference points to help illustrate approximate locations of the subject photo during the April 20, 2018 inspection.

Inspection Photos

Location Name: RMP-CO-EVERETT-UPRR #1

API: 05-039-06428



**Photo 1.** Photo taken from the western battery location, facing West. Gully erosion is evident and BMP is in disrepair. Operator has failed to complete final reclamation activities.

Inspection Photos  
Location Name: RMPCO-EVERETT-UPRR #1  
API: 05-039-06428




**Photo 2.** Photo taken from the gully erosion along the western battery location, facing West. Erosion continues west, off location.

Inspection Photos  
Location Name: RMP-CO-EVERETT-UPRR #1  
API: 05-039-06428



**Photo 3.** Photo taken from the western battery location, facing East. Vegetation at the battery location is not reflective of reference area vegetative level and does not meet Rule 1004 standards. Operator has failed to complete final reclamation activities.



**Photo 4.** Photo taken from the northern battery location, facing West. See comments under Photo 3.

Inspection Photos  
Location Name: RMPCO-EVERETT-UPRR #1  
API: 05-039-06428



**Photo 5.** Photo taken of the eastern well location on November 3, 2017, facing East. Operator has not reclaimed the location per Rule 1004 standards. The location has not been contoured to match the surrounding landscape. Rill erosion evident along the eastern cut slope.



**Photo 6.** Photo taken of the eastern well location on April 20, 2018, facing East. Operator has failed to complete final reclamation activities.

Inspection Photos  
Location Name: RMPCO-EVERETT-UPRR #1  
API: 05-039-06428



**Photo 7.** Photo taken from the eastern well location on November 3, 2017, facing South. See comments under Photo 6.



**Photo 8.** Photo taken from the eastern well location on November 3, 2017, facing North. See comments under Photo 6.