

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2018

Submitted Date:

04/24/2018

Document Number:

689100136

FIELD INSPECTION FORM

Loc ID 335560 Inspector Name: LUJAN, CARLOS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Middleton, Brett		bmiddleton@caerusoilandgas.com	Sr. Environmental Specialist
Janicek, Jake		JJanicek@caerusoilandgas.com	EHS Professional
Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region
Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW
Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454721	SPILL OR RELEASE	AC			-	SPILL/RELEASE POINT	EI

General Comment:

Environmental inspection conducted in response to a flowline spill reported on 04/19/2018 (Spill report doc #401614178, Spill/Release Point ID #454721). Sunny day, temperature around 62 oF. The lease operator identified a leaking flowline associated with the D09A 6C-9 well. The flowline was isolated, purged, repaired and taken out of service. Area was excavated with a hydrovac. Samples from the bottom and wall of the excavation indicated that some HC impact still remained. Additional excavation was done. Caerus environmental contractor, LTE, took additional samples. Casrus will report the findings when results are available. Depending on the results, Caerus will either backfill the excavation or present a form 27 remediation work plan.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 454721 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: CONDENSATE

Estimated Spill Volume: _____

Comment: Produced water and condensated. The flowline has been repaired. Confirmation samples are in the lab.

Corrective Action: If confirmation samples show no impact on walls and bottom of the excavation, request spill report closure. If analytical results indicate that impact has been larger than expected, submit a form 27 remediation work plan.

Date: 05/04/2018

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689100137	PhotoReport Caerus D09A flowline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4443954