

DOE PM-2-31
Api# -045-045-07036
Inspection # 689701292



Battery sign



Location photo

DOE PM-2-31
Api# -045-045-07036
Inspection # 689701292



Tubing off the edge of location. 39.48637 108.04253

DOE PM-2-31
Api# -045-045-07036
Inspection # 689701292



**Ruts are creating erosion riling at top switch back. Sediment build up in ditch.
(39.48567 108.04314)**

DOE PM-2-31
Api# -045-045-07036
Inspection # 689701292



Erosion of hillside from ditch run off at top switch back.
(39.48567 108.04314)

DOE PM-2-31
Api# -045-045-07036
Inspection # 689701292



**Sediment build up over straw bales used for check dams @ Switch back
(39.48597 108.04075)**

DOE PM-2-31
Api# -045-045-07036
Inspection # 689701292



**Erosion of hillside from ditch run off and rilling of roadside @ (39.48523
108.04113)**

DOE PM-2-31
Api# -045-045-07036
Inspection # 689701292



**Erosion of hillside from ditch run off and rilling of roadside @ (39.48523
108.04113)**

DOE PM-2-31
Api# -045-045-07036
Inspection # 689701292



Sediment build up in ditch @ (39.48382 108.04018)

DOE PM-2-31
Api# -045-045-07036
Inspection # 689701292



Erosion of hillside from ditch run off @ (39.48382 108.04018)