

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2018

Submitted Date:

04/18/2018

Document Number:

684905316**FIELD INSPECTION FORM**Loc ID 318942 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Findings:**16 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Dale	(719) 729-3391	dalehartwoc@fairpoint.net	All Inspections
James, Steve	(303) 893-2438	steve@westernoperating.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111624	PIT	AC	09/23/1999		-	HOOZIE-BJOLIN 1	AC
242550	WELL	PR	02/02/2001	OW	123-10341	HOOZEE-BJOLIN 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tanks have been labeled		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Incorrect sign at pump jack		
Corrective Action:	Install sign to comply with rule 210.b.	Date:	06/18/2018
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Tested number @ 1040hr. As of 1500hr, no response.

Corrective Action: Install sign to comply with rule 210.b.

Date: 05/18/2018

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at treater, engine, engine exhaust		
Corrective Action:	Comply with rule 603.f. Properly treat or dispose in accordance with Rule 907.f.	Date:	05/18/2018
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment around pump jack has been removed.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	barbed wire		
Corrective Action:		Date:	

Equipment:

Type: Prime Mover	# 1		corrective date
Comment:	gas engine		
Corrective Action:		Date:	

Type: Horizontal Heater Treater	# 0		
Comment:	removed		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	containers- 1 propane		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.536910,-103.642840
Comment:	Stained soil at loadout has been removed				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 111624 Type: PIT API Number: - Status: AC Insp. Status: ACFacility ID: 242550 Type: WELL API Number: 123-10341 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadComment: Bradenhead not plumbed to surface.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 111624Lat: 40.536872Long: -103.643533Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: MeshNetting Condition: GoodComment: Corrective Action: Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YESComment: Produced water pit with adjacent skim. Stained soil in produced water pit.Corrective Action: Date: 05/18/2018**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401613063	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4438422
684905317	Site photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4438410