

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/18/2018

Submitted Date:

04/18/2018

Document Number:

689300920

FIELD INSPECTION FORM

Loc ID 335525 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1400
City: DENVER State: CO Zip: 80202

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------------------------------|---------------------------------|
| , Laramie | | cogccnotifications@laramie-energy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 299165 | WELL | PR | 11/22/2009 | GW | 045-17582 | KNAUS 30-04C | PR |
| 299204 | WELL | PR | 11/22/2009 | GW | 045-17608 | KNAUS 30-04A | PR |

General Comment:

[Routine Field Inspection](#)

| Location | | | |
|--|---------------------------|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Emergency Contact Number: | | | |
| Comment: | 1-800-891-6191 | | |
| Corrective Action: | | | Date: |
| Good Housekeeping: | | | |
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | WEEDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Livestock panels | | |
| Corrective Action: | | | Date: |
| Type | SEPARATOR | | |
| Comment: | Live stock panels | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Vertical Heated Separator | # 2 | | corrective date |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Chemical unit at Wellhead | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------------|-----|--|-------|
| Type: Plunger Lift | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------|----------|-----------|---------|--------|
| CONDENSATE | 3 | OTHER | STEEL AST | | |
| Comment: | 250 BBL | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|------------------|
| Metal | Adequate | Walls Insufficient | Base Sufficient | Inadequate |
| Comment: | Holes in tank battery containment | | | |
| Corrective Action: | Repair or install berms or other secondary containment devices per Rule 605.a.(4). | | | Date: 05/18/2018 |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 299165 Type: WELL API Number: 045-17582 Status: PR Insp. Status: PR

Producing Well

Comment: [Well Producing on plunger lift](#)

Corrective Action:

Date:

Facility ID: 299204 Type: WELL API Number: 045-17608 Status: PR Insp. Status: PR

Producing Well

Comment: [Well Producing on plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | Pass | | | |
| Seeding | Pass | | | | | |
| | | Ditches | Pass | | | |
| Compaction | Pass | | | | | |
| Gravel | Pass | | | | | |
| | | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------------------|---|
| 401613075 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4438431 |
| 689300921 | DocNum: 689300920.4/18/18 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4438421 |