

# Inspection Photos

API: 05-067-09374

Operator: HILCORP ENERGY COMPANY

Inspection Date: 4/12/2018



**Photo 1. View of the project area from the southeastern corner facing center.**



**Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is progressing, largely with western wheatgrass (*Pascopyrum smithii*).**





**Photo 3. View of the southern portion of the project area from the southeastern corner facing westward.**



**Photo 4. View of the northern project area from the northeastern corner facing westward. Stormwater diversion appears to flow to the northeastern corner.**





**Photo 5. View of erosional channel where concentrated stormwater from well pad diversion erodes the northeastern corner of the project area. Stormwater controls are needed to de-energize flows and contain sediment.**





**Photo 6. Guy line anchor not marked.**