

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2018

Submitted Date:

04/25/2018

Document Number:

680402697

FIELD INSPECTION FORM

Loc ID 334554 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1400
City: DENVER State: CO Zip: 80202

Findings:

- 10 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Bankert, Wayne	970-683-5419	cogccnotifications@laramie-energy.com	All inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259437	WELL	PR	09/13/2002	GW	077-08730	BUZZARD CREEK 15-10	PR
262735	WELL	PR	02/01/2018	GW	077-08754	BUZZARD CREEK 15-16	PR
263989	WELL	IJ	02/01/2017	DSPW	077-08765	Buzzard Creek 22-3	AC

General Comment:

[Routine UIC inspection.](#)

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action			Date:
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence. Injection wellhead inside housing		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Panel fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Pump inside housing		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLs	STEEL AST		39.271219,-107.754237
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLs	HEATED STEEL AST		39.271886,-107.753666
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities			
Facility ID: <u>259437</u>	Type: <u>WELL</u>	API Number: <u>077-08730</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>Plunger lift</u>			
Corrective Action:		Date:	
Facility ID: <u>262735</u>	Type: <u>WELL</u>	API Number: <u>077-08754</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>Plunger lift</u>			
Corrective Action:		Date:	
Facility ID: <u>263989</u>	Type: <u>WELL</u>	API Number: <u>077-08765</u>	Status: <u>IJ</u> Insp. Status: <u>AC</u>
Underground Injection Control			
UIC Violation: _____	Maximum Injection Pressure: _____		
<u>UIC Routine</u>			
Inj./Tube: Pressure or inches of Hg <u>500</u>	Previous Test Pressure _____	MPP _____	Inj Zone: <u>OHCRK</u>
(e.g. 30 psig or -30" Hg)			Last MIT: <u>11/28/2017</u>
TC: Pressure or inches of Hg <u>30</u>	Previous Test Pressure _____		AnnMTReq: _____
Brhd: Pressure or inches of Hg <u>0</u>	Previous Test Pressure _____		
Comment: <u>Routine UIC inspection. Active injection at time of inspection. Last MIT 11/28/2017.</u>			
Corrective Action:		Date:	
Method of Injection: <u>PUMP FEED</u>			
Test Type: _____	Tbg psi: _____	Csg psi: _____	BH psi: _____
Insp. Status: _____			
Comment: _____			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	Secondary containment of chemicals.

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680402705	Inspection photos 4/24/2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4445349