

# **Inspection Photos**

API: 05-067-09069

Operator: HILCORP ENERGY COMPANY

Inspection Date: 4/12/2018



**Photo 1. View of the project area from the southeastern corner of the working area facing center.**





**Photo 2. View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing, largely with western wheatgrass (*Pascopyrum smithii*), crested wheatgrass (*Agropyron cristatum*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).**





**Photo 3. View of the northern portion of the project area from the northeastern portion facing westward.**





**Photo 4. View of musk thistles (*Carduus nutans*) within the northwestern portion of the project area.**





**Photo 5. View of more musk thistles in the northern interim reclamation area.**





**Photo 6. View of erosional channel approximately 1.5 feet wide and deep in the northeastern portion of the project area.**





**Photo 7. View of another erosional channel forming in the northeastern portion of the project area.**