

Inspection Photos
Location Name: ROLLIE J. VINCENT A #1
Facility ID #244760



Photo 1. Wellhead



Photo 2. Tank battery

Inspection Photos
Location Name: ROLLIE J. VINCENT A #1
Facility ID #244760




Photo 3. Stained soil around wellhead



Photo 3. Stained soil near heated treater under valve

Inspection Photos
Location Name: ROLLIE J. VINCENT A #1
Facility ID #244760



Photo 5. Unmarked riser with no LO/TO