

Inspection Photos
Location Name: Fitzhugh #6, REM #10228
API: 05-007-05038



Crude oil AST without secondary containment.



Stained soil beneath load out valve.

Inspection Photos
Location Name: Fitzhugh #6, REM #10228
API: 05-007-05038



Land farm treatment area for REM #10228.



Fitzhugh #6 well head and pump jack.

Inspection Photos
Location Name: Fitzhugh #6, REM #10228
API: 05-007-05038



Fitzhugh #6 well head and surrounding soil are stained.



Stained soil beneath load out valve on unused AST.

Inspection Photos
Location Name: Fitzhugh #6, REM #10228
API: 05-007-05038



Fitzhugh #15 PA marker and abandoned flow line.



Fitzhugh #7 casing is stained with oil.

Inspection Photos
Location Name: Fitzhugh #6, REM #10228
API: 05-007-05038



Excavation around Fitzhugh #7 well head.



Fluids present in Fitzhugh #7 well bore. PA marker is not welded on.

Inspection Photos
Location Name: Fitzhugh #6, REM #10228
API: 05-007-05038



Fitzhugh #15 PA marker and abandoned flow lines.



Land farm treatment cell.

Inspection Photos
Location Name: Fitzhugh #6, REM #10228
API: 05-007-05038



Containment berm along northern edge of land farm treatment cell.



Overview photo with 300 bbl. AST and land farm treatment cell.