

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2018

Submitted Date:

04/28/2018

Document Number:

691200058**FIELD INSPECTION FORM**

Loc ID 310579 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**19 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>
Leonard, Mike		mike.leonard@state.co.us	
Precup, Jim		james.precup@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293802	WELL	SI	01/01/2016	OW	123-26619	HERTZKE N 1-7	SI
437292	TANK BATTERY	AC	04/14/2009		-	HERTZKE N-65N67W 1SWNE	IO

**General Comment:**

### Location

<b>Lease Road:</b>			
Type	Main		
comment:	Adequate		
Corrective Action		Date:	
Type	Access		
comment:	2-Track Agricultural road to Hertzke N 1-7 (API# 05-123-26619) well is adequate.		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Battery sign still shows P&A'd well, Hertzke N 1-12 (API#05-123-26555).		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	<input style="width: 500px;" type="text"/>	
Corrective Action:	<input style="width: 500px;" type="text"/>	Date: <input style="width: 100px;" type="text"/>

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hertzke N 1-7 (API#05-123-26619): Iron panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chain link - 6'		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	ECD fencing is chain link- 6' / iron panel.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Chain link - 6'		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	Gas meter has been removed from meter run.		
Corrective Action:		Date:	

Type: Emission Control Device	# 1	
Comment:	Controls tank VOCs	
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:	Hertzke N 1-7 (API# 05-123-26619)	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:	2 wells are commingled at separator. 1.) Hertzke N 1-7 (API# 05-123-26619) 2.) Hertzke N 1-11 (API# 05-123-26618)	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		
Comment:	3" load line on water vault has no cap/screen to prevent animal/avian ingress.				
Corrective Action:	Rule 324 A,a, Pollution. Wildlife protections devices not adequate. Install or repair wildlife protection equipment.				Date: 05/10/2018

**Paint**

Condition	
Other (Content)	
Other (Capacity)	60 Bbls
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:	Date:				
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.427400,-104.846060
Comment:	3" equalizer line between oil tanks				
Corrective Action:	Date:				

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b><u>Berms</u></b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
<b><u>Venting:</u></b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b><u>Flaring:</u></b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 293802 Type: WELL API Number: 123-26619 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: May be under waiver for MIT.

Corrective Action:

Date:

**BradenHead**

Comment: Braidenhead appears plumbed to surface.

Corrective Action:

Date:

Facility ID: 437292 Type: TANK API Number: - Status: AC Insp. Status: IO

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: May be under waiver

Corrective Action:

Date:

**BradenHead**

Comment: Braidenhead appaers plumbed to surface

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<u>Centalized Battery.</u>	evinsb	04/28/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200059	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4448844">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4448844</a>