

Inspection Photos
Location Name: Boxer 25, 29, & 26 Tank Battery
Facility ID: 439100
Inspection Date: April 27, 2018



Photo #1 – Crude oil tank battery with battery sign.

Photo #2 – View from NW of tank battery documents that operator has improved berms on location.

Inspection Photos

Location Name: Boxer 25, 29, & 26 Tank Battery

Facility ID: 439100

Inspection Date: April 27, 2018



Photo #3 – Unused junk at NE corner of facility.



Photo #4 – 300 bbl produced water AST has been removed, additional work required to remove unused equipment and to reclaim former earthen berm.



Inspection Photos

Location Name: Boxer 25, 29, & 26 Tank Battery

Facility ID: 439100

Inspection Date: April 27, 2018



Photo #5 – Unused stairs remaining at NE corner of evaporation pit.



Photo #6 – Flowline riser at SE corner of former produced water AST location.



Inspection Photos

Location Name: Boxer 25, 29, & 26 Tank Battery

Facility ID: 439100

Inspection Date: April 27, 2018



Photo #7 – Unused pipe on south side of former produced water AST berm.



Photo #8 – Unused pipe and stairway on south side of facility.



Inspection Photos

Location Name: Boxer 25, 29, & 26 Tank Battery

Facility ID: 439100

Inspection Date: April 27, 2018



Photo #9 – View of facility from south side of fence demonstrates surface grading and erosion control efforts made by operator.



Photo #10 – View from NE corner of facility demonstrates ongoing surface grading efforts made by operator.

Refer to Remediation Project #1551 for documentation of ongoing site investigation and remediation efforts in this area.



Inspection Photos

Location Name: Boxer 25, 29, & 26 Tank Battery

Facility ID: 439100

Inspection Date: April 27, 2018



Photo #11 – View of NE corner of repaired pit berm.



Photo #12 – View looking SW over evaporation pit documents berm repair and weed control efforts.



Inspection Photos

Location Name: Boxer 25, 29, & 26 Tank Battery

Facility ID: 439100

Inspection Date: April 27, 2018



Photo #13 – Photo from previous FIR (dated 3/2/2018) shows conditions of eroded area south of location, looking north.



Photo #14 – Photo from inspection date shows that area from previous photo has been graded by operator.

Refer to Remediation Project #9362 for ongoing site investigation and remediation efforts in this area.

