

**Inspection Photos**  
**Location Name: State CF #1**  
**API: 05-067-07927**



**Sections of 3" fiberglass pipe being replaced with steel pipe.**

**Repaired section of transfer line on location.**

**Inspection Photos**  
**Location Name: State CF #1**  
**API: 05-067-07927**



04.30.2018 14:13

**Pipe line route south of the State CF #1 location.**



04.30.2018 14:13

**Subsidence along pipe line route on location.**

**Inspection Photos**  
**Location Name: State CF #1**  
**API: 05-067-07927**



**Southern edge of location along pipe line route.**



**Erosion along pipe line right of way.**

**Inspection Photos**  
**Location Name: State CF #1**  
**API: 05-067-07927**



**New sections of steel pipe being installed.**



**Transition from fiberglass pipe to new steel pipe.**

**Inspection Photos**  
**Location Name: State CF #1**  
**API: 05-067-07927**



**New section of steel pipe in area where failure occurred.**



**Stained soil along flow path of release.**