

Inspection Photos

04/30/2018

Operator: WIEPKING-FULLERTON ENERGY LLC -
96340

Location ID: 436744

Inspection Doc. Number: 682503289
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 436744



Photo 1: Photo taken from the north end of the location, facing southeast. Photo shows overview of the location



Photo 2: Photo taken from the north end of the location, facing southwest. Photo shows overview of the location

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 436744



Photo 3: Photo taken from the location, facing west. Photo shows striations in the soil surface, suggesting area was reseeded was conducted, possibly using a no-till seed drill.



Photo 4: Photo taken from the location, facing south. Photo shows striations in the soil surface, suggesting area was reseeded was conducted, possibly using a no-till seed drill.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 436744



Photo 5: Photo taken from the access road entrance, facing northeast. Photo shows additional work appears to have been conducted, however, it also appears a two-pronged ripper only cut through areas of the ruts within the road. Compaction alleviation does not appear to have conducted in accordance to reclamation requirements. Compaction concerns remain on access road.



Photo 6: Photo taken from the access road entrance, facing northeast. See comments under photo 5.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 436744



Photo 7: Photo taken from the access road, facing northeast. Photo shows inspector tested the access road for compaction concerns. Photo shows soils within the areas of the ruts, where a ripper did pass through, were easier to penetrate.



Photo 8: Photo taken from the access road, facing northeast. Photo shows inspector tested the access road for compaction concerns. Photo shows soils **OUTSIDE** the areas of the ruts, where a ripper **DID NOT** pass through, were difficult to penetrate; inspector was only able to easily penetrate to top couple inches of soil. Compaction concerns remain evident.



Photo 9: Photo taken from the adjacent reference area. Photo shows inspector was able to easily penetrate the soils in the reference area.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 436744



Photo 10: Photo taken from the access road to the north of the location. Photo shows sign where operator appears to have ended reclamation of the access road. Access road continues ~1/4 mile to the north. Operator remains responsible for the reclamation of these areas of access road.



Photo 11: Photo taken from the sign seen in photo 10 within the access road. Photo shows remaining section of access road to the north. Photo shows no reclamation activities appear to have been performed; gravel remains on road, access road has not been re-contoured, re-graded or had compaction alleviation conducted. Operator remains responsible for reclamation of access road.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 436744



Photo 11: Photo taken from the area where the access road joins the east/west ranch road, north of the sign seen in photo 10, facing south. Photo shows remaining section of access road where no reclamation activities appear to have been performed; gravel remains on road, access road has not been re-contoured, re-graded or had compaction alleviation conducted. Operator remains responsible for reclamation of access road.



Photo 12: Photo taken from the area where the access road joins the east/west ranch road, north of the sign seen in photo 10, facing southwest. Photo shows remaining section of access road where no reclamation activities appear to have been performed; gravel remains on road, access road has not been re-contoured, re-graded or had compaction alleviation conducted. Operator remains responsible for reclamation of access road.