

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/26/2018

Submitted Date:

05/02/2018

Document Number:

689401184

**FIELD INSPECTION FORM**

Loc ID 312460 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10150  
Name of Operator: BLACK HILLS PLATEAU PRODUCTION LLC  
Address: 1515 WYNKOOP ST STE 500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221666	WELL	PA	07/21/2014	GW	077-08268	FEDERAL (UTE WATER) 6-2	PA

**General Comment:**

Inspection in response to complaint Doc#200445784 . Any corrective actions not addressed from previous inspections are still applicable.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume	corrective date
Type: Plunger Lift		# 0	
Comment:	<input type="text"/>		
Corrective Action:			Date:
Type: Vertical Separator		# 0	
Comment:	<input type="text"/>		
Corrective Action:			Date:

**Venting:**

Yes/No		
Comment:	<input type="text"/>	
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	<input type="text"/>
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 221666 Type: WELL API Number: 077-08268 Status: PA Insp. Status: PA

**Complaint**

Comment: Complainant noticed gas smell on two separate occasions while in the area. FIU staff did transects with gas meter around location and near by pipeline riser. No indication of gas at that time. No odor observed by staff at that time either. Scheduled follow up inspection with NW Field supervisor to do FLIR survey of location.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689401185	Federal (Ute Water) 6-2 Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4453002">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4453002</a>