

Inspection Photo
GGU Miller 33C-31-691
API# 045-18239
Inspection # 689301063



Location photo # 1



Location photo #2

Inspection Photo
GGU Miller 33C-31-691
API# 045-18239
Inspection # 689301063



Location photo # 3 storm water Erosion



Location photo #4 Rutted location

Inspection Photo
GGU Miller 33C-31-691
API# 045-18239
Inspection # 689301063



Location photo # 5 Rutted location



Location photo #6

Inspection Photo
GGU Miller 33C-31-691
API# 045-18239
Inspection # 689301063



Location photo # 7 storm water erosion



**Location photo # 8 storm water erosion
near heater treater**

Inspection Photo
GGU Miller 33C-31-691
API# 045-18239
Inspection # 689301063



Location photo # 9 storm water erosion near heater treater



Location photo # 10 storm water erosion near heater treater

Inspection Photo
GGU Miller 33C-31-691
API# 045-18239
Inspection # 689301063



Location photo # 11 Storm water North of heater-treater



Location photo #12 Storm water North of heater-treater

Inspection Photo
GGU Miller 33C-31-691
API# 045-18239
Inspection # 689301063



Location photo # 13, faded tank label/sign



Location photo # 14 Peeling sign