

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2018

Submitted Date:

05/01/2018

Document Number:

681701025**FIELD INSPECTION FORM**Loc ID 450344 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Aaron		aaron.trujillo@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
LARA-MESA, SUSANA	(303) 825-4822	slaramesa@kpk.com	
Leonard, Mike		mike.leonard@state.co.us	
		cogcc@kpk.com	
Young, Rob		rob.young@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
102701	PIT	AC			-	BOXER LEASE Production Pit	EI
102703	PIT	AC			-	BOXER LEASE WEST SKIM PIT	AC
439100	TANK BATTERY	AC	09/26/2014		-	Boxer 25,26,29 Battery	EI

**General Comment:**

COGCC environmental field inspection of KPK Boxer 25, 29, &amp; 26 Tank Battery facility. Follow-up to Field Inspection Report #681700992 and Remediation Projects #9362 &amp; #1551.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Operator has removed 300 bbl produced water AST documented in previous FIR. Bullplugged 2" flowline riser daylighting at SE corner of former produced water AST location, unused pipe remains along south side of location, and unused stairs remain at NE corner of produced water pit. Junk pipe and unused equipment also remain at NE corner of facility (near VHT shed). See photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	08/01/2018

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: Localized accumulations of oil-stained soil noted in previous FIR have been removed.

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Inspector Name: Arauza, Steven

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent		Adequate	
Comment:	Berms repaired and localized accumulations of oily waste were removed in response to previous FIR. See photos.				
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities								
Facility ID:	102701	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	102703	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	AC
Facility ID:	439100	Type:	TANK	API Number: -	Status:	AC	Insp. Status:	EI

**Environmental**

**Spill/Remediation:**

Comment: [Operator has filed eForm 27 Supplemental Site Investigation and Remediation Workplans, as required by previous FIR. Refer to Remediation Projects #1551 and #9362.](#)

Corrective  
Action:

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_

Wildlife Protection Devices (fired vessels): \_\_\_\_\_

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: On date of inspection, operator was in process of making improvements for stormwater and erosion control on location. Additional reclamation of former produced water AST berm required. See photos. Refer to Remediation Projects #1551 and #9362 for operator's site investigation, remediation, and reclamation plans for south end of facility.

Corrective Action: Comply with 1003 Series interim reclamation rules at former produced water AST location.

Date: 06/01/2018

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Skimming/Settling      Lined: NO      Pit ID: 102703      Lat: 40.102504      Long: -103.891893

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

Date: c

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment: Operator was required by previous FIR (doc #681700992) to provide pit closure documentation for former skim pit. Required documentation has not been received as of 5/1/2018.

Corrective Action

Provide pit closure, remediation, and reclamation documentation via eForm 27.

Date: 04/21/2018

Type: Evaporation      Lined: NO      Pit ID: 102701      Lat: 40.102312      Long: -103.891915

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

Date: c

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

<b>Netting:</b>		
Netting Type:	Netting Condition:	
Comment:		
Corrective Action		Date:
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	Earthen berms have been improved and weeds controlled in response to previous FIR. See photos.	
Corrective Action		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401626265	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4450609">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4450609</a>
681701027	Field photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4450608">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4450608</a>