

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2018

Submitted Date:

05/01/2018

Document Number:

691300148**FIELD INSPECTION FORM**
 Loc ID 323643 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	
Kraich, Adam	970-420-0536	Adam.Kraich@state.co.us	(Area 117) Field Operations

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245515	WELL	PR	01/29/1987	GW	123-13310	BRANTNER 30-9	PR
435349	TANK BATTERY	AC	12/09/2013	LO	-	Brantner Tank Battery 435349	AC

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red iron

Corrective Action:

Date:

Equipment:

corrective date

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment: Vessel is not anchored per rule 603.h.(2)B. See photos.

Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.

Date: 05/31/2018

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	FIBERGLASS AST		,
Comment: Tank is not anchored per rule 603.h.(2)B. See photos.					
Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.					Date: 05/31/2018

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent	Adequate	
Comment: SHares berms with production tank.						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent	Adequate	
Comment: Shares berms with produced water tank.						
Corrective Action:						Date:
Venting:						
Yes/No						
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected FacilitiesFacility ID: 245515 Type: WELL API Number: 123-13310 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 435349 Type: TANK API Number: - Status: AC Insp. Status: AC**Producing Well**

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

Well and battery are located in FEMA floodplain.

kraicha

05/01/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401626732	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4450941
691300149	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4450938