

Inspection Photos
Location Name: UPRR PAN AM AP #1
Facility ID # 241568



Photo 1. Wellhead



Photo 2. Tank battery

Inspection Photos
Location Name: UPRR PAN AM AP #1
Facility ID # 241568



Photo 3. Stained soil near load out and west side of tank.



Photo 4. Unmarked riser and stained soil center of crude oil Tanks

Inspection Photos
Location Name: UPRR PAN AM AP #1
Facility ID # 241568



Photo 5. Stained soil south side of tanks



Photo 6. Stained soil near outlet of tank

Inspection Photos
Location Name: UPRR PAN AM AP #1
Facility ID # 241568




Photo 7. Stained soil near transfer pump



Photo 8. Unmarked riser on east side of crude oil tanks

Inspection Photos
Location Name: UPRR PAN AM AP #1
Facility ID # 241568



Photo 9. 2 unmarked risers inside containment near meter house, second riser is not visible in picture.



Photo 10. Fence in disrepair