

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401635840  
Date Received:  
05/10/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
.		<a href="mailto:cogcc.inspections@crestonepr.com">cogcc.inspections@crestonepr.com</a>

COGCC INSPECTION SUMMARY:

FIR Document Number: 682403506  
Inspection Date: 04/25/2018 FIR Submit Date: 04/30/2018 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Company Number: 10633  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 428577

Location Name: Ruegge Facility Number: 4H-N165 County: \_\_\_\_\_  
Qtrqr: SWS Sec: 4 Twp: 1N Range: 65W Meridian: 6  
W  
Latitude: 40.074992 Longitude: -104.677897

FACILITY - API Number: 05-123-00 Facility ID: 428577

Facility Name: Ruegge Facility Number: 4H-N165  
Qtrqr: SWS Sec: 4 Twp: 1N Range: 65W Meridian: 6  
W  
Latitude: 40.074992 Longitude: -104.677897

CORRECTIVE ACTIIONS:

1 CA# 116140

Corrective Action: Comply with Rule 1002. Corrective action date is being back-dated to when the Operator should have been in compliance with this rule. Date: 03/25/2018

Response: CA COMPLETED Date of Completion: 05/10/2018

Operator Comment: Topsoil at the location was salvaged and has been stockpiled. Topsoil in areas where the former Stelling facility was did not exist and all fill material was removed or recontoured during the initial construction operations. Approximately 6200 cubic yards of segregated topsoil is stockpiled on the pad.

Topsoil along flowline areas had been salvaged utilizing a double ditching method, and segregated during

excavation, then backfilled immediately. Vegetation was grubbed along the flowline corridor as appropriate. Currently there is 1400 feet of open flowline. Topsoil was salvaged down to 12in. An estimated 3088 cubic yards of segregated topsoil is stockpiled along side.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

--

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Approximately 6200 cubic yards of segregated topsoil is stockpiled on the pad.

Currently there is 1400 feet of open flowline. Topsoil was salvaged down to 12in. An estimated 3088 cubic yards of segregated topsoil is stockpiled along side.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: John Gardner

Signed: \_\_\_\_\_

Title: Sr. Env. Specialist

Date: 5/10/2018 10:05:47 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files