

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2018

Submitted Date:

05/10/2018

Document Number:

689301093**FIELD INSPECTION FORM**

Loc ID 324005 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|----------------|---|--|
| Elsener, Garrett | (303)-565-4600 | COGCC.inspections@caerus oilandgas.com | all Piceance inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 211469 | WELL | PR | 01/08/1998 | GW | 045-07229 | SAVAGE 2-31 | PR |

General Comment:[Routine Field Inspection](#)

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date:

Good Housekeeping:

| | | | |
|--------------------|--------|-------|--|
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WEEDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|---------------------|-------|--|
| Type | SEPARATOR | | |
| Comment: | Barbed wire fencing | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Barbed wire fencing | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | | |
|--------------------------|-----|-------|--|-----------------|
| | | | | corrective date |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | Date: | | |
| Type: Deadman # & Marked | # 4 | | | |
| Comment: | | | | |
| Corrective Action: | | Date: | | |

| | | | |
|-----------------------------------|-----|--|-------|
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 2 | 300 BBLS | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|---------------|--|
| Condition | Inadequate | |
| Other (Content) | Methanol Tank | |
| Other (Capacity) | 500 Gallon | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 211469 | Type: | WELL | API Number: | 045-07229 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

| Environmental | |
|--------------------------------|--|
| Spill/Remediation: | |
| Comment: | |
| Corrective Action: | Date: |
| Emission Control Burner (ECB): | |
| Comment: | |
| Pilot: | Wildlife Protection Devices (fired vessels): YES |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | | | | | | |
| Gravel | | | | | | |
| Slope Roughening | | | | | | |
| | | Gravel | | | | |
| | | Compaction | | | | |
| Ditches | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 689301094 | Inspection photo 689301094 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4459889 |