

Interim Reclamation Inspection

May 9, 2018

Operator: CRESTONE PEAK RESOURCES OPERATING LLC- #10633

Location ID: 435070

Inspection Document #: 682403556

Weld County, CO

SWNW Section 19 T3N R68W

Chris Binschus

Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 1. Photo taken from the northeastern location on May 9, 2018, facing South. Operator failed to perform interim reclamation activities by 4/30/18. Interim reclamation areas are not reflective of reference area vegetative levels. Undesirable weed species were observed throughout and there is not uniform establishment of desirable species.



Photo 2. Photo taken from the eastern location on May 9, 2018, facing North. Photo of *Chorispora tenella* (Purple Mustard) which is an invasive species.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 3. Photo taken from the eastern location on May 9, 2018, facing South. See comments under Photo 1.



Photo 4. Photo taken from the southeastern location on May 9, 2018, facing West. Photo illustrates establishment of desirable species. This area does not appear to need additional reclamation activities.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 5. Photo taken from the southern location on May 9, 2018, facing East. See comments under Photo 1. This area has a high abundance of Kochia and other undesirable species.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 6. Close-up photo taken from the previous photo location (Photo 5). Photo illustrates the Kochia rosettes and cheatgrass with little, to no, establishment of desirable species.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 7. Photo taken from the western location on May 9, 2018, facing South. See comments under Photo 1.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070




Photo 8. Reference photo taken from the western location on May 9, 2018, facing South. Photo illustrates that interim areas are not reflective of reference area vegetation.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 9. Photo taken from the northern location on May 9, 2018, facing East. See comments under Photo 1.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070




Photo 10. Photo taken from the northern location on May 9, 2018, facing North. Photo illustrates that interim areas are not reflective of reference area vegetation.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 11. Photo taken from the central location on May 9, 2018, facing South. See comments under Photo 1.