

Final Reclamation and Stormwater Inspection

May 14, 2018

Operator: SRC ENERGY INC- #10311

Location ID: 424103

Inspection Document #: 682403572

Weld County, CO

SESE Section 4 T3N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HOAGLAND /44-4
Location ID: 424103



Aerial imagery photo taken 2011 before oil and gas development. Red "x" indicates approximate southeast corner of tank battery and red dots are the approximate well locations.

Inspection Photos
Location Name: HOAGLAND /44-4
Location ID: 424103



Aerial imagery photo taken 2017. Photo illustrates the well location, battery location, and access roads.

Inspection Photos
Location Name: HOAGLAND /44-4
Location ID: 424103



Photo 1. Photo taken from the entrance of the well location off 3rd street, facing West. Appears the Operator is attempting to reclaim the access road with the evidence of drilling rows and straw crimped mulch. Some germination of grass species was evident along portions of the access road but did not observe any reference area vegetation (alfalfa). Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards.

Photo 2. Photo taken from a portion of the access road, facing East. See comments under Photo 1.

Inspection Photos
Location Name: HOAGLAND /44-4
Location ID: 424103



Photo 3. Photo taken from the well location, facing South. Did not observe any germination of grass species or alfalfa throughout any portion of the well location.



Photo 4. Photo taken from the tank battery location, facing Northeast. Operator has failed to reclaim a portion of the access road.

Inspection Photos
Location Name: HOAGLAND /44-4
Location ID: 424103



Photo 5. Photo taken from the northeast battery location, facing South. Appears the Operator has performed final reclamation activities. Perimeter fence has been installed around the battery location. Some germination of grass species was evident along portions of the access road but did not observe any reference area vegetation (alfalfa).



Photo 6. Photo taken from the northeast battery location, facing West. See comments under Photo 5.