



**Photo 1. View of the project area from the northeastern corner facing center.**



**Photo 2. View of the northern portion of the project area from the northeastern corner of the working area facing westward. Revegetation is progressing on fill slope.**



**Photo 3. View of the eastern portion of the project area from the southeastern corner of the working area facing northward. Slope is recently disturbed and seeded.**



**Photo 4. View of debris in the southern portion of the working area, needs to be removed.**



**Photo 5. View of the southwestern portion of the project area.**



**Photo 6. View of recently disturbed right of way. Area is seeded, but needs careful monitoring due to the aerial extent of disturbance and dry growing conditions.**



**Photo 7. Closeup view of seedlings in area recently seeded.**