

**Inspection Photo**  
**Clough 521-16**  
**API# 045-13505**  
**Inspection # 689301117**



**Location Photo #1,**



**Location Photo #2,**



**Inspection Photo**  
**Clough 521-16**  
**API# 045-13505**  
**Inspection # 689301117**



**Location Photo #3, Erosion on the west side of the access road, near location. Looking uphill**



**Location Photo #4, Erosion on the side of the access road looking South downhill .**



**Inspection Photo**  
**Clough 521-16**  
**API# 045-13505**  
**Inspection # 689301117**



**Location Photo #5, Corner of access road  
near road closed gates**



**Location Photo #6, Bottom of the curve near  
the culvert.**