

Inspection Photo
Federal RWF 312-16
API# 045-10028
Inspection # 689301119



Location Photo #1,



**Location Photo #2, Erosion on South west
end of location**

Inspection Photo
Federal RWF 312-16
API# 045-10028
Inspection # 689301119



Location Photo #3, storm water issue



Location Photo #4, ditch along south side of location, storm water issue

Inspection Photo
Federal RWF 312-16
API# 045-10028
Inspection # 689301119



Location Photo #5, Storm Water issue on west end of location



Location Photo #6, Storm Water issue on west end of location

Inspection Photo
Federal RWF 312-16
API# 045-10028
Inspection # 689301119



Location Photo #7, Storm water issue on north side of location



Location Photo #8, Storm water issue on north side of location

Inspection Photo
Federal RWF 312-16
API# 045-10028
Inspection # 689301119



Location Photo #9, Culvert under access road downhill side.



Location Photo #10, Culvert under access road downhill side.

Inspection Photo
Federal RWF 312-16
API# 045-10028
Inspection # 689301119



Location Photo #11, Erosion near end of location by access road



Location Photo #12, Erosion near end of location by access road

Inspection Photo
Federal RWF 312-16
API# 045-10028
Inspection # 689301119



**Location Photo #13, Ditch Erosion along
access road near the Y**



**Location Photo #14, Ditch Erosion along
access road near the Y**