

Well Name : Bullseye 22

API # : 067-09814



Photo 1: Wellhead sign previous inspection.



Photo 2: Wellhead sign.

Well Name : Bullseye 22

API # : 067-09814



Photo 3: Below grade tank labels previous inspection.



Photo 4: New tank signage.

Well Name : Bullseye 22

API # : 067-09814



Photo 5: Risers at wellhead previous inspection.



Photo 6: Wellhead after risers abandoned.

Well Name : Bullseye 22

API # : 067-09814



Photo 7: Flow lines at separator previous inspection.



Photo 8: Separator after flow lines abandoned.

Well Name : Bullseye 22

API # : 067-09814



Photo 9: Breach in berm NE corner with erosion channel in background previous inspection.



Photo 10: Breach in berm with erosion channel in background. Corrective action not completed.

Well Name : Bullseye 22

API # : 067-09814



Photo 11: Breach in berm and undercut straw wattle previous inspection.



Photo 12: Breach in berm and undercut straw wattle. Corrective action not completed.

Well Name : Bullseye 22

API # : 067-09814



Photo 13: Erosion channel on fill slope.



Photo 14: Erosion channel on fill slope.
Corrective action not completed.

Well Name : Bullseye 22

API # : 067-09814



Photo 15: Cut slope slide area behind tank battery previous inspection.



Photo 16: Cut slope slide area behind tank battery. Corrective action not completed.

Well Name : Bullseye 22

API # : 067-09814



Photo 17: Slide pushing into tank battery fencing previous inspection.



Photo 18: Slide pushing into tank battery fencing. Corrective action not completed.

Well Name : Bullseye 22

API # : 067-09814



Photo 19: View at top of cut slope slide area.



Photo 20: Full waddles at bottom of fill slope.