

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2018

Submitted Date:

05/18/2018

Document Number:

680602647**FIELD INSPECTION FORM**Loc ID 306916 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------------|---------------------------------|
| Beebe, Sabre | | Sabre.Beebe@bp.com | All Inspections |
| , | | SanJuanCOGCC@bp.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 277747 | WELL | PR | 11/07/2014 | GW | 067-09044 | MELTON MAYFIELD 2 | RI |

General Comment:

This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 277747 | Type: | WELL | API Number: | 067-09044 | Status: | PR | Insp. Status: | RI |
| | | | | | | | | | |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is surrounded by pinyon juniper woodland and irrigated grass field.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment Stakes and marker debris observed within the eastern interim reclamation area.Corrective Action Remove debris.Date 06/22/2018Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

| | | | |
|--|--|---|------------------------|
| Date Final Reclamation Started: _____ | | Date Final Reclamation Completed: _____ | |
| Final Land Use: _____ | | | |
| Reminder: _____ | | | |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | | | |
| Well plugged _____ | Pit mouse/rat holes, cellars backfilled _____ | | |
| Debris removed _____ | No disturbance /Location never built _____ | | |
| Access Roads _____ | Regraded _____ | Contoured _____ | Culverts removed _____ |
| Gravel removed _____ | | | |
| Location and associated production facilities reclaimed _____ | | Locations, facilities, roads, recontoured _____ | |
| Compaction alleviation _____ | | Dust and erosion control _____ | |
| Non cropland: Revegetated 80% _____ | | Cropland: perennial forage _____ | |
| Weeds present _____ | | Subsidence _____ | |
| 1004.d. FINAL VEGETATION TRANSECT | | | |
| TRANSECT RESULTS OF DISTURBED AREA% _____ | | | |
| TRANSECT RESULTS OF REFERENCE AREA% _____ | | | |
| TOTAL % OF DESIRABLE VEGETATION COVER _____ | | | |
| VEGETATIVE COVER _____ | | | |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | | | |
| Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | | | Date _____ |
| Overall Final Reclamation _____ | Well Release on Active Location <input type="checkbox"/> | Multi-Well Location <input type="checkbox"/> | |

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [Stormwater erosion appears to be controlled at this time.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 680602648 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4467350 |