

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/18/2018

Submitted Date:

05/18/2018

Document Number:

684905439**FIELD INSPECTION FORM**

Loc ID 437140 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1801 BROADWAY #500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                       | Comment                         |
|--------------|-------|-----------------------------|---------------------------------|
| ,            |       | cogccinspections@gwogco.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type         | Status | Status Date | Well Class | API Num | Facility Name                          | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|--|-------------|
| 443796      | TANK BATTERY | AC     | 10/30/2015  |            | -       | Cornish Off-site Tank Battery 08-399HN | AC          |

**General Comment:**

**Location**Overall Good: ☒

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | TANK LABELS/PLACARDS                    |       |            |
| Comment:             | No capacity on condensate tank          |       |            |
| Corrective Action:   | Install sign to comply with rule 210.d. | Date: | 07/18/2018 |
| Type                 | BATTERY                                 |       |            |
| Comment:             |   |       |            |
| Corrective Action:   |   | Date: |            |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | SEPARATOR    |       |  |
| Comment:           | barbed wire  |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           | barbed wires |       |  |
| Corrective Action: |              | Date: |  |

|                                   |                |       |                 |
|-----------------------------------|----------------|-------|-----------------|
| <b>Equipment:</b>                 |                |       | corrective date |
| Type: Bird Protectors             | # 4            |       |                 |
| Comment:                          |                |       |                 |
| Corrective Action:                |                | Date: |                 |
| Type: Emission Control Device     | # 3            |       |                 |
| Comment:                          | unlit while SI |       |                 |
| Corrective Action:                |                | Date: |                 |
| Type: Gas Meter Run               | # 1            |       |                 |
| Comment:                          |                |       |                 |
| Corrective Action:                |                | Date: |                 |
| Type: Horizontal Heated Separator | # 1            |       |                 |
| Comment:                          |                |       |                 |
| Corrective Action:                |                | Date: |                 |

**Tanks and Berms:**

|                    |   |                        |           |         |                       |       |
|--------------------|---|------------------------|-----------|---------|-----------------------|-------|
| Contents           | # | Capacity               | Type      | Tank ID | SE GPS                |       |
| CONDENSATE         | 1 | OTHER                  | STEEL AST |         | 40.483840,-104.470120 |       |
| Comment:           |   | No capacity, see signs |           |         |                       |       |
| Corrective Action: |   |                        |           |         |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

|                    |   |          |                |         |                       |       |
|--------------------|---|----------|----------------|---------|-----------------------|-------|
| Contents           | # | Capacity | Type           | Tank ID | SE GPS                |       |
| PRODUCED WATER     | 1 | 100 BBLs | PBV FIBERGLASS |         | 40.493840,-104.470120 |       |
| Comment:           |   |          |                |         |                       |       |
| Corrective Action: |   |          |                |         |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                        |                     |             |       |
|--------------------|----------|------------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall)    | Permeability (Base) | Maintenance |       |
|                    |          |                        |                     |             |       |
| Comment:           |          | Shared with condensate |                     |             |       |
| Corrective Action: |          |                        |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

| Inspected Facilities |        |       |      |             |   |         |    |               |    |
|----------------------|--------|-------|------|-------------|---|---------|----|---------------|----|
| Facility ID:         | 443796 | Type: | TANK | API Number: | - | Status: | AC | Insp. Status: | AC |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Fail            | Gravel                  | Pass                  |               |                          |         |

Comment: [Stormwater erosion around ECD, S of ECD.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 06/18/2018

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 684905440    | Site photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468353">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468353</a> |