



**Photo 1. View of the project area from the southeastern corner facing center.**



**Photo 2. View of the southern portion of the project area from the southeastern corner facing westward.**



**Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward.**



**Photo 4. View of musk thistles from the previous season.**



**Photo 5. View of stormwater controls within the western portion of the project area appear to be added after erosional channel was formed.**



**Photo 5. View of stormwater controls within the western portion of the project area appear to be added after erosional channel was formed.**



**Photo 5. View of culverts at the entrance to the access road need to be removed.**