

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2018

Submitted Date:

05/13/2018

Document Number:

689301101

FIELD INSPECTION FORM

Loc ID 426533 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10500
Name of Operator: COACHMAN ENERGY OPERATING COMPANY LLC
Address: 1125 17TH STREET SUITE 410
City: DENVER State: CO Zip: 80202

Findings:

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Canepa, Frank	720-279-0009	fcanepa@coachmanenergy.com	
Neyeska, Mut	303-296-3535	neyeska@cynosure-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426529	WELL	PR	10/14/2013	GW	045-21180	FEDERAL 6/7-14-21	PR
426539	WELL	PR	10/17/2013	GW	045-21181	FEDERAL 6/7-15-21	PR
426544	WELL	PR	10/14/2013	GW	045-21182	FEDERAL 6/7-13-21	PR
426545	WELL	PR	07/28/2013	GW	045-21183	FEDERAL 6/7-16-21	PR
427243	WELL	IJ	04/06/2015	DSPW	045-21277	PWD Federal 21-6-91	IJ

General Comment:

[Routine Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Emergency Contact Number:		
Comment:	1-866-217-8087	
Corrective Action:		Date:

Good Housekeeping:		
Type	OTHER	
Comment:	Stained Material in Tank Battery Containmnet	
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.	Date: 06/13/2018
Type	DEBRIS	
Comment:		
Corrective Action:		Date:
Type	WEEDS	
Comment:		
Corrective Action:		Date:
Type	TRASH	
Comment:		
Corrective Action:		Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:		
Type	WELLHEAD	
Comment:	Livestock panels	
Corrective Action:		Date:
Type	PIT	
Comment:	Netting around Pit with fence	
Corrective Action:		Date:

Equipment:			corrective date
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:

Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at Wellhead		
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	STEEL AST		,
Comment:	Centralized Battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	400 BBLs	HEATED STEEL AST		,
Comment:	Centralized Battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	7	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
			Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities

Facility ID: 426529 Type: WELL API Number: 045-21180 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 426539 Type: WELL API Number: 045-21181 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 426544 Type: WELL API Number: 045-21182 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 426545 Type: WELL API Number: 045-21183 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 427243 Type: WELL API Number: 045-21277 Status: IJ Insp. Status: IJ

Completion

Operation:

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Gravel				
Slope Roughening						
				Material Handling And Spill Prevention		
Gravel						
		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401638777	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4462189
689301102	Inspection photo 689301102	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4462183