

# Argenta 34-10 #34-3

Corrective Actions Taken on the Argenta 34-10 #34-3 INC.





**Hilcorp Energy Company**

**DWR ARGENTA 34-10 34-3**  
**# 70911-F FEE DWR#70911-F**  
**API NO. 05-067-08640**  
**NE/NE, 990' FNL & 990' FEL**  
**SEC.34 T034N R010W NMPM**  
**LA PLATA COUNTY, CO ELEV 6712**  
**LAT:36° 09' 08" LONG:107° 54' 53"**  
**EMERGENCY NUMBER (505) 324-5170**  
**NO SMOKING NO TRESPASSING**





Storm Water management controls have been established to stabilize erosion in the Eastern portion of the project area.



Corrective action taken for Photo 7 from inspection report.





Corrective action taken for Photo 7 from inspection report.



All rig anchors on the well pad have been properly marked.



Corrective action taken for Photo 8 from inspection report.





Corrective action taken for Photo 8 from inspection report.



Storm Water management controls have been established to stabilize erosion in the Northeastern portion of the project area.





All wood, liner, and trash debris have been removed from the project area and properly disposed of.



Corrective action taken for Photo 6 from inspection report.



Storm Water management controls have been established to stabilize erosion along access road near well pad.



Corrective action taken for Photo 8 from inspection report.





Corrective action taken for Photo 8 from inspection report.