

Argenta 34-10 #33-3

Corrective Actions Taken on the Argenta 34-10 #33-3 INC.



Hilcorp Energy Company

ARGENTA 34-10 33-3 FRC
DWR # 70909-F FEE
API NO. 05-067-08641
NW/NE, 990' FNL & 1425' FEL
SEC.33,T-034-N,R-010-W,NMPM
LA PLATA COUNTY, COLORADO
LAT:37.1521194 N LONG:107.93412 W
EMERGENCY NUMBER (505) 324-5170
NO SMOKING NO TRESPASSING



Storm Water management controls have been established to stabilize erosion in the Southeastern portion of the project area.



Corrective action taken for Photo 4 & 5 from inspection report.

Storm Water management controls have been established to stabilize erosion in the North and Northwest portion of the project area.



Corrective action taken for Photo 6 from inspection report.



Corrective action taken for Photo 6 from inspection report.

Storm Water management controls have been established to stabilize erosion along the access road near well pad.



Corrective action taken for Photo 7 from inspection report.



Corrective action taken for Photo 7 from inspection report.