

Argenta 34-10 #32-1

Corrective Actions Taken on the Argenta 34-10 #32-1 INC.



Wattles on the northeast edge of project area have been cleaned and maintained to stabilize erosion.



Corrective action taken for Photo 6 from inspection report.

Storm Water management controls have been established to stabilize erosion of fill slope bare soil areas in eastern project area until their is a more favorable time for seeding the area.



Corrective action taken for eastern fill slope from inspection report findings.

All liner material and trash debris have been removed from the project area and properly disposed of.



Corrective action taken for Photo 7 from inspection report.



Corrective action taken for Photo 7 from inspection report.