

Argenta 34-10 #34-1A

Corrective Actions Taken on the Argenta 34-10 #34-1A INC.



Storm Water management controls have been established to stabilize erosion in the Northeastern portion of the project area.



Corrective action taken for Photo 5 from inspection report.

All rig anchors on well pad have been properly marked.



Corrective action taken for Photo 6 from inspection report.