

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2018

Submitted Date:

05/21/2018

Document Number:

688301833**FIELD INSPECTION FORM**
 Loc ID 431995 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 19160Name of Operator: CONOCO PHILLIPS COMPANYAddress: P O BOX 2197City: HOUSTON State: TX Zip: 77252-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dixon, Jennifer	(701) 264-2041	jennifer.a.dixon@conocophillips.com	Regulatory Coordinator
ConocoPhillips		COPColoradoReg@conocophillips.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431992	WELL	TA	10/18/2016	OW	005-07204	Converse Family 6 1H	TA

**General Comment:**Bradenhead Test Inspection

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 855-595-8258

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	barabed wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 0		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 0		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 0		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment:					
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 431992 Type: WELL API Number: 005-07204 Status: TA Insp. Status: TA**BradenHead**

Comment: Form 42 #401644007, digital gauge  
-5 psi prior to test, 2 min 40 sec to blowdown through needle nose vavle, Casing 0.1 psi  
prior to test

0 min BHd 0 psi, casing 0 psi  
5 min BHd 0 psi, casing 0 psi  
10 min BHd 0 psi, casing 0 psi  
15 min BHd 0 psi, casing 0 psi

Form 17 is attached.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688301835	Conoco Phillips Converse Family 6 1H wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4470089">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4470089</a>
688301836	Converse Family 6 1H Form 17	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4470090">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4470090</a>