

Well Name : Carter Ute 107
API # : 067-07459




Photo 1: Wellhead sign previous inspection.



Photo 2: Wellhead sign.

Well Name : Carter Ute 107

API # : 067-07459



Photo 3: Impacted soil and gravel NW side of pump jack previous inspection.



Photo 4: Mediated area on NW side of pump jack.

Well Name : Carter Ute 107

API # : 067-07459



Photo 5: Impacted soil and gravel along concrete base of pump jack previous inspection.



Photo 6: Mediated area along concrete base of pump jack.

Well Name : Carter Ute 107

API # : 067-07459



Photo 7: Insulation along NW perimeter of location previous inspection.



Photo 8: Insulation debris removed along NW perimeter.

Well Name : Carter Ute 107

API # : 067-07459



Photo 9: Impacted soil and gravel on S and SW side of compressor unit previous inspection.



Photo 10: Mediated soil and gravel on S and SW sides of compressor unit.

Well Name : Carter Ute 107
API # : 067-07459



Photo 11: Location overview.



Photo 12: Location overview.

Well Name : Carter Ute 107

API # : 067-07459



Photo 13: Location overview.



Photo 14: Location overview.