

**Inspection Photo
O'toole A3
API# 045-13752
Inspection # 689301172**



Location Photo #1



Location Photo #2 Sign peeling on tank

**Inspection Photo
O'toole A3
API# 045-13752
Inspection # 689301172**



Location Photo #3, sign peeling on tank



Location Photo #4, stained material in battery containment

**Inspection Photo
O'toole A3
API# 045-13752
Inspection # 689301172**



**Location Photo #5, stained material in
battery containment**

**Location Photo #6, stained material in
battery containment**

**Inspection Photo
O'toole A3
API# 045-13752
Inspection # 689301172**



Location Photo #7, Ditch erosion along side of road on east side

Location Photo #8 , Ditch erosion along side of road on east side. Looking down hill



**Inspection Photo
O'toole A3
API# 045-13752
Inspection # 689301172**



Location Photo #9, Ditch erosion along side of road on West side. Looking down hill

Location Photo #10, Ditch erosion along side of road on West side. Looking downhill

**Inspection Photo
O'toole A3
API# 045-13752
Inspection # 689301172**



Location Photo #11, Ditch erosion along side of road on east side near curve

Location Photo #12, Ditch erosion along side of road on east side near curve

**Inspection Photo
O'toole A3
API# 045-13752
Inspection # 689301172**



Location Photo #13, Ditch erosion along side of road on east side at the curve

Location Photo #14, Ditch erosion along side of road on east side at the curve

