

**Inspection Photos**  
**Location Name: Dilka 6-12**  
**API: 05-123-23783**



**Photo 1: Location**



**Photo 2: Wellhead**



**Inspection Photos**  
**Location Name: Dilka 6-12**  
**API: 05-123-23783**




**Photo from prior inspection for comparison**




**Photo 3: Stained soil outside of separator**

**Inspection Photos**  
**Location Name: Dilka 6-12**  
**API: 05-123-23783**



**Photo from prior inspection for comparison**



**Photo 4: Stained soil in separator**



**Inspection Photos**  
**Location Name: Dilka 6-12**  
**API: 05-123-23783**



**Photo 5: Stormwater erosion NW of wellhead**



**Photo 6: Stormwater erosion S of battery**

