

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2018

Submitted Date:

05/18/2018

Document Number:

688400169**FIELD INSPECTION FORM**
 Loc ID 432988 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10311Name of Operator: SRC ENERGY INCAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**22 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		cogccinspections@srcenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432990	WELL	PR	04/02/2015	OW	123-37396	SRC Union 12-5CHZ	PR
432991	WELL	PR	02/19/2015	OW	123-37397	SRC Union A-5NHZ	PR
432992	WELL	PR	04/02/2015	OW	123-37398	SRC Union A-5CHZ	PR
432993	WELL	PR	04/03/2015	OW	123-37399	SRC Union C-5NHZ	PR
432994	WELL	PR	07/28/2017	OW	123-37400	SRC Union 12-5NHZ	PR
435075	WELL	PR	04/04/2015	OW	123-38451	SRC Union C-5CHZ	PR
453869	SPILL OR RELEASE	AC	01/29/2018		-	SRC Union Pad Oil Spill	AC

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	6' chain link		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	6' chain link		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 6		

Comment:		Telemetry Equipment		Date:	
Corrective Action:				Date:	
Type: Compressor	# 1				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:		Separator venting gas pumper on location making adjustments repairs being made at time of inspection			
Corrective Action:		Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date:	04/29/2018
Type: Emission Control Device	# 4				
Comment:					
Corrective Action:				Date:	
Type: Vertical Separator	# 7				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 6				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment:		Methonal pumps w/containment			
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:				Date:	
Type: VRU	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 10				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 5				
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	400 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	12	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES		
Comment:	Mechanical issue with 1 Horizontal separator Pumper on location making repairs repairs being made at time of inspection		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 04/29/2018

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

<b>Inspected Facilities</b>			
Facility ID: <u>432990</u>	Type: <u>WELL</u>	API Number: <u>123-37396</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment: <u>PR</u>			
Corrective Action:		Date:	
<b><u>Complaint</u></b>			
Comment: <div style="border: 1px solid black; padding: 10px; margin-top: 5px;"> <p>Field Inspector Assigned: Jason E. Gomez</p> <p>Complaint Received:</p> <p>Date: 4-27-2018</p> <p>Complaint Contacted:</p> <p>Date: 4-27-2018    Time 1200 Hrs</p> <p>Location #:    432988</p> <p>Inspection Document #: 688400169</p> <p>Nature of complaint: Venting gas</p> <p>Field Inspector Actions:</p> <p>On 4-27-2018, I was contacted by COGCC staff in reference to a complaint received by the COGCC in reference to possible venting gas from a location located south east of the Union reservoir.</p> <p>On 4-27-2018 I went to the SRC Energy Union 11-5D location located SE of Union reservoir. Upon arrival I observed a SRC lease operator making repairs to a horizontal separator on location. I spoke with the SRC pumper who indicated she was making the repair to the separator due to a malfunction of the separator, she indicated when she arrived the separator was venting gas on a (PRV) pressure relief valve on the separator. After speaking with the lease operator I performed a complete site inspection on the Union see inspection document # 688400169 for detail of inspection</p> <p>No violation of COGCC rules were observed at the time of the inspection.</p> <p>All information reviewed and site inspection information were submitted to the complaint specialist for further review.</p> </div>			
Corrective Action:		Date:	
<b><u>BradenHead</u></b>			
Comment: <u>Appears to be plumbed to surface</u>			
Corrective Action:		Date:	
Facility ID: <u>432991</u>	Type: <u>WELL</u>	API Number: <u>123-37397</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment: <u>PR</u>			
Corrective Action:		Date:	

<b><u>BradenHead</u></b>			
Comment: <span style="color: blue;">Appears to be plumbed to surface</span>		Date: _____	
Corrective Action: _____		Date: _____	
Facility ID: <u>432992</u>	Type: <u>WELL</u>	API Number: <u>123-37398</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment: <span style="color: blue;">PR</span>		Date: _____	
Corrective Action: _____		Date: _____	
<b><u>BradenHead</u></b>			
Comment: <span style="color: blue;">Appears to be plumbed to surface</span>		Date: _____	
Corrective Action: _____		Date: _____	
Facility ID: <u>432993</u>	Type: <u>WELL</u>	API Number: <u>123-37399</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment: <span style="color: blue;">PR</span>		Date: _____	
Corrective Action: _____		Date: _____	
<b><u>BradenHead</u></b>			
Comment: <span style="color: blue;">Appears to be plumbed to surface</span>		Date: _____	
Corrective Action: _____		Date: _____	
Facility ID: <u>432994</u>	Type: <u>WELL</u>	API Number: <u>123-37400</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment: <span style="color: blue;">PR</span>		Date: _____	
Corrective Action: _____		Date: _____	
<b><u>BradenHead</u></b>			
Comment: <span style="color: blue;">Appears to be plumbed to surface</span>		Date: _____	
Corrective Action: _____		Date: _____	
Facility ID: <u>435075</u>	Type: <u>WELL</u>	API Number: <u>123-38451</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment: <span style="color: blue;">PR</span>		Date: _____	
Corrective Action: _____		Date: _____	
<b><u>BradenHead</u></b>			
Comment: <span style="color: blue;">Appears to be plumbed to surface</span>		Date: _____	
Corrective Action: _____		Date: _____	
Facility ID: <u>453869</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>AC</u> Insp. Status: <u>AC</u>
<b><u>Producing Well</u></b>			
Comment: <span style="color: blue;">PR</span>		Date: _____	
Corrective Action: _____		Date: _____	

BradenHead		
Comment:	<div>Appears to be plumbed to surface</div>	
Corrective Action:	<div></div>	Date: <div></div>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401645412	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4467456">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4467456</a>
688400174	Location Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4467453">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4467453</a>