

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2018

Submitted Date:

05/17/2018

Document Number:

689401232**FIELD INSPECTION FORM**Loc ID 312511 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Graves, Jim	(970) 858-8550	mrinc20@qwestoffice.net	Operation Manager
Engineering		dnr_cogccengineering@state.co.us	All Engineering
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	All Inspections
Reid, Jordan	(970) 563-4000	maralextechjr@gmail.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221818	WELL	SI	09/01/1989	GW	077-08420	FEDERAL 35-2	TA

**General Comment:**

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable. This well is included in the AOC # 1V-609

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:	Main BLM road heavily rutted and has signs of sediment migration from seasonal conditions and recreational traffic.		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted Emergency Contact Number 1-970-585-8550

Corrective Action:

Date:

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Risers have been disconnected, marked with spray paint and only have tape covering ends.		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

corrective date

Type: Gas Meter Run	# 1		
Comment:	Disconnected		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**Facility ID: 221818 Type: WELL API Number: 077-08420 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: No current Form 4 on file for continued TA status. According to AOC 1V-609 order #11 annual submission is still required.

Corrective Action: A Sundry Notice, Form 4, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation.

Date: 06/18/2018

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Main BLM road heavily rutted and has signs of sediment migration from seasonal conditions and recreational traffic. Stormwater erosion appears to be controlled on the location at this time.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: NO Pit ID: \_\_\_\_\_ Lat: 39.316670 Long: -108.299167

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: NO 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Type: \_\_\_\_\_ Lined: NO Pit ID: \_\_\_\_\_ Lat: 39.316892 Long: -108.299428

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type:	Netting Condition:	
Comment:		
Corrective Action		Date:
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard:
Comment:		
Corrective Action		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401646411	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468287">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468287</a>
689401233	Federal 35-2 Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468257">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468257</a>