

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2018

Submitted Date:

05/17/2018

Document Number:

689401238**FIELD INSPECTION FORM**Loc ID 312507 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Engineering		dnr_cogccengineering@state.co.us	All Engineering
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	All Inspections
Graves, Jim	(970) 858-8550	mrinc20@qwestoffice.net	Operation Manager
Reid, Jordan	(970) 563-4000	maralextechjr@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221808	WELL	SI	11/10/1992	GW	077-08410	FEDERAL 25-3	TA

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable. This well is included in the AOC # 1V-609.

Location				
Lease Road:				
Type	Access			
comment:	See stormwater section			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted Emergency Contact Number 1-970-585-8550			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Meter house has been disconnected and damaged.			
Corrective Action:	Remove to comply with Rule 603.f.			Date: 06/18/2018
Type	UNUSED EQUIPMENT			
Comment:	Risers have been disconnected, marked with spray paint and only have tape covering ends.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected FacilitiesFacility ID: 221808 Type: WELL API Number: 077-08410 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: No current Form 4 on file for continued TA status. According to AOC 1V-609 order #11 annual submission is still required.

Corrective Action: A Sundry Notice, Form 4, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation.

Date: 06/18/2018

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts	Fail					

Comment: [Culvert on access road has collapsed.](#)Corrective Action: [Install or repair required BMPs](#)

Date: 06/18/2018

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401646413	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468289
689401239	Federal 25-3 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468262