

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2018

Submitted Date:

05/18/2018

Document Number:

691200115**FIELD INSPECTION FORM**

Loc ID 310388 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections
Precup, Jim		james.precup@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292414	WELL	SI	05/01/2017	OW	123-26334	STROMBERGER 13-32	TA

General Comment:

Location**Lease Road:**

Type	Main		
comment:	Main road to Stromberger 13-32 (API #05-123-26334) battery is adequate		
Corrective Action		Date:	
Type	Access		
comment:	Acess road to Stromberger 13-32 (API #05-123-26334) is non-existent. Also gate is locked at county road with a lock that will not open with the key provided to COGCC by Noble. Had to climb over gate and walk about 1/4 mile to well through newly planted corn. Location is not accessible during normal business hours.		
Corrective Action	Provide key, combinations, or altenate method of access. Repair and maintain lease road. Comply with Rule 204.	Date:	06/18/2018

Overall Good: ☐**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Statewide unused equipment, weeds, waste, and trash requirements. Found various unused equipment and debris at wellsite.		
Corrective Action:	Comply with Rule 603.f .	Date:	06/18/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	WELLHEAD		
Comment:	Stromberger 13-32 (API #05-123-26334) has iron panel fence.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		

Comment: 48" ECD controls oil tank VOCs		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 2	
Comment:		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		Date:
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	35 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: Shares berms w/ produced oil tanks & produced H2O tank.				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: Shares berms w/ produced oil tanks & produced H2O vault.				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.479920,-104.842453
Comment:					

Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Metal	Adequate	Walls Sufficient	Base Sufficient
Comment: Shares berms w/ produced H2O tank & vault.			
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 292414 Type: WELL API Number: 123-26334 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: SI. Appears to be TA as all other equipment downstream from well master valve has been disconnected.Corrective Action: Date: **BradenHead**Comment: Bradenhead appears plumbed to surface.Corrective Action: Date: **COGCC Comments**

Comment	User	Date
Several other wells that had previously been associated with this facility appear to have been P&A'd. Stromberger 1-13, 13-31, & 13-35.	evinsb	05/18/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401646237	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468123
691200116	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468110